

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2024

Submitted Date:

10/15/2024

Document Number:

717000069**FIELD INSPECTION FORM**Loc ID 319986 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202126	WELL	PR	01/01/2023	GW	001-07531	HORTH R 2	SI

**General Comment:**

Location				
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:		Adequate		
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds around well head			
Corrective Action:	Rule 606: Weeds, dead weeds. Within the designated setback (25 feet around any and all equipment), remove trash, debris and weeds per Rule 606. Corrective Action Date 11/1/2024. See attached photo # 1			Date: 11/01/2024
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**Facility ID: 202126 Type: WELL API Number: 001-07531 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: 02/02/2024 Annual Brhd Completed? \_\_\_\_\_Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0Comment: Appeared to be plumbed to the surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Summary</p> <p>On Wednesday October 2nd 2024 at approximately (11:47am) I, Inspector Chane Finkenbinder, conducted an on-site inspection.</p> <p>Operator: KP KAUFFMAN COMPANY INC</p> <p>Location name: HORTH R #2</p> <p>API # 05-001-07531</p> <p>Location ID #: 319986</p> <p>County: Adams</p> <p>While there, I observed a (shut in) well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Rule 606: Weeds, dead weeds. Within the designated setback (25 feet around any and all equipment), remove trash, debris and weeds per Rule 606. Corrective Action Date 11/1/2024. See attached photo # 1</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	finkenbc	10/15/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403958608	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6747535">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6747535</a>
717000070	Inspection photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6747530">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6747530</a>