

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/22/2024

Submitted Date:

10/23/2024

Document Number:

693807847

FIELD INSPECTION FORM

Loc ID 316830 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10841

Name of Operator: AMERICAN HELIUM OPERATING LLC

Address: 600 TRAVIS STREET SUITE 5050

City: HOUSTON State: TX Zip: 77002

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Roberts, Jake		jroberts@americanhelium.us	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Joyner, Ryan	970.385.6289	rjoyner@blm.gov	Tres Rios
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263816	WELL	TA	07/01/2004	GW	113-06105	HORSE RANGE FEDERAL 19-24	TA

General Comment:

ECMC staff performed a routine field inspection on 10/22/2024.

Issues were found requiring corrective action. See inspection text and photos for details.

Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location				
Lease Road:				
Type	Main			
comment:				
Corrective Action	L		Date:	
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign at location entrance. Sign not legible Sign not updated to reflect current operator			
Corrective Action:	Install sign to comply with Rule 605.g.		Date:	11/22/2024
Emergency Contact Number:				
Comment:	435-631-2237 Wrong Emergency contact number			
Corrective Action:	Install sign to comply with Rule 605.d.		Date:	11/22/2024
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Bradenhead	# 1			corrective date
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:			Date:	
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	



Inspected Facilities									
Facility ID:	263816	Type:	WELL	API Number:	113-06105	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder:			
Comment:		<div>Defined Inactive 07/31/2004 Last MIT 7/29/2022</div>							
Corrective Action:								Date:	
BradenHead									
Date of Last Brhd Test:		06/15/2023		Annual Brhd Completed?		No			
Last Brhd Test Results		Initial Surf Csg Pressure:		9		Fluid Type:		NONE	
		End Surf Csg Pressure:		0					
Comment:		<div>No annual bradenhead test Form 17 on file.</div>						11/22/2024	
Corrective Action:		<div>Submit Form 17 as directed by Rule 419.c</div>						Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807850	Inspection photos 10/22/2024.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6757497