

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403968496

Date Received:

10/23/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714300121

Inspection Date: 08/20/2024

FIR Submit Date: 09/05/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: CRESTONE PEAK RESOURCES OPERATING LLC

Company Number: 10633

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

#### LOCATION - Location ID: 322858

Location Name: OSKARSON E UNIT 62N68W Number: 33SWSWM ULTIWELL County: \_\_\_\_\_

Qtrqtr: SWS W Sec: 33 Twp: 2N Range: 68W Meridian: 6

Latitude: \_\_\_\_\_ Longitude: \_\_\_\_\_

#### FACILITY - API Number: 05-123- -00 Facility ID: 487569

Facility Name: Oskarson E Unit 1 Number: \_\_\_\_\_

Qtrqtr: SWS W Sec: 33 Twp: 2N Range: 68W Meridian: 6

Latitude: \_\_\_\_\_ Longitude: \_\_\_\_\_

### CORRECTIVE ACTIONS:

1 CA# 198382

Corrective Action: E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 905. If soil is to be stockpiled on location Operator shall install a sign to denote if the stockpile is clean or contaminated. If soil stockpile is contaminated Operator will collect a soil sample from underneath the observed soil stockpile area prior to spill closure.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 10/14/2024

Operator has reported that the open holes and stockpiles that were previously reported were present only during

Operator Comment:	site decommission operations. All holes have now been backfilled after samples were collected.
ECMC Decision:	
ECMC Representative:	

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	CA follow-up has been completed for this location.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Ashley Noonan	Signed:
Title: Sr Regulatory Analyst	Date: 10/23/2024 7:55:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403968497	Inspection Report Resolution

Total Attach: 1 Files