

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/14/2024

Submitted Date:

10/17/2024

Document Number:

713601534

**FIELD INSPECTION FORM**Loc ID 321163 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10626

Name of Operator: DOVER ATWOOD CORPORATION

Address: 1875 HARSH AVENUE SE

City: MASSILLON State: OH Zip: 44646

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kelly, George	(888) 858-7886	envexbaca@aol.com	
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256504	WELL	PR	08/04/2010	GW	009-06598	BEAR CREEK 1-3	RI
478536	TANK BATTERY	AC	11/11/2020		-	BEAR CREEK-631S43W	RI

**General Comment:**

This is a reclamation inspection of the BEAR CREEK #1-3 wellsite and associated tank battery.  
Operator is directed to perform corrective actions immediately.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	There are unused parts, equipment, and containers that need to be removed.		
Corrective Action:	Comply with Rule 606.		Date: 10/24/2024
Type	WEEDS		
Comment:	There are tall weed debris around the equipment which is a fire hazard.		
Corrective Action:	Comply with Rule 606.		Date: 10/24/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1		Open Top		,	
Comment:	There is no netting on the open top tank to prevent wildlife entry.					
Corrective Action:	Comply with 902.b. Install or repair wildlife protection equipment.				Date:	10/24/2024

**Paint**

Condition	<input type="text"/>	
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		
Comment:	The secondary containment is inadequate to contain a spill.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.			Date:

**Venting:**

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date:

**Flaring:**

Type	<input type="text"/>	
------	----------------------	--

Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403961790	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6750917">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6750917</a>
713601535	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6750870">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6750870</a>