

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403970181

Date Received:

10/25/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Dolezal, Pat

970-332-3585

pat.dolezal@ownresources.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 698602330

Inspection Date: 08/30/2024

FIR Submit Date: 09/17/2024

FIR Status: _____

Inspected Operator Information:

Company Name: OWN RESOURCES OPERATING LLC

Company Number: 10699

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

LOCATION - Location ID: 303519

Location Name: JONES-61N44W Number: 19NWNE County: YUMA

Qtrqtr: NWNE Sec: 19 Twp: 1N Range: 44W Meridian: 6

Latitude: 40.044870 Longitude: -102.328680

FACILITY - API Number: 05-125-

-00

Facility ID: 253225

Facility Name: JONES

Number: 2

Qtrqtr: NWNE Sec: 19 Twp: 1N Range: 44W Meridian: 6

Latitude: 40.044870 Longitude: -102.328680

CORRECTIVE ACTIONS:

1 CA# 198857

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 10/18/2024

Response: CA COMPLETED

Date of Completion: 10/24/2024

Operator
Comment:

Hauled in gravel to fill erosion, installed diverter uphill from locaiton

ECMC Decision:

Date: 04/19/2024

Date of Completion: 10/24/2024

Hauled in gravel to fill erosion, installed diverter uphill from location

Comment:

Signed:

Date: 10/25/2024 8:56:56 AM

403970181	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Page 2 of 2