



403966788

Hilcorp Anderson 3-5H

067-09948

Photo document

10/23/2024

 **Hilcorp Energy Company**
EMERGENCY CONTACT (505) 324-5170 OR 911
ANDERSON 2-5H
178' FSL 154' FEL
SE/SE SEC 5P T32N R6W
LATITUDE: 37.039460
LONGITUDE: -107.515330
API# 05-067-09949-00
LEASE # FEE
LA PLATA COUNTY, COLORADO

 **Hilcorp Energy Company**
EMERGENCY CONTACT (505) 324-5170 OR 911
ANDERSON 3-5H
155' FSL 172' FEL
SE/SE SEC 5P T32N R6W
LATITUDE: 37.039400
LONGITUDE: -107.515400
API# 05-067-09948-00
LEASE # FEE
LA PLATA COUNTY, COLORADO

10.23.2024



10.23.2024

Revegetation of fill slope
predominately weeds/undesireables



10.23.2024

Red Cedar gathering equipment



Open ended poly flowline, no OOSLAT



10.23.2024



10.23.2024



Intial pressure up on chart recorder

10.23.2024



Testing head and high pressure line to truck

10.23.2024



10.23.2024



Ending chart

10.23.2024



Rill erosion on cut slope and sediment migration

10.23.2024



10.23.2024



10.23.2024

Kochia NW corner of pad



10.23.2024

Access road and vegetation

