

State of Colorado  
Energy & Carbon Management Commission



Document Number:  
403985757

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Date Received:  
11/06/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:  
1 of 1 CAs from the FIR responded to on this Form  
1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>ECMC Enforcement</u>		<u>dnr_ecmcenforcement@state.co.us</u>
<u>BEAR STACY</u>		<u>stacy@strachanexploration.com</u>
<u>HARMS JASON</u>		<u>jason@strachanexploration.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 713601490  
Inspection Date: 10/03/2024 FIR Submit Date: 10/04/2024 FIR Status:

Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC Company Number: 83130  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

LOCATION - Location ID: 324827

Location Name: HELFRICH-619S50W Number: 4SESW County: KIOWA  
Qtrqtr: SESW Sec: 4 Twp: 19S Range: 50W Meridian: 6  
Latitude: 38.427871 Longitude: -103.017976

FACILITY - API Number: 05-061-00 Facility ID: 212992

Facility Name: HELFRICH Number: 1  
Qtrqtr: SESW Sec: 4 Twp: 19S Range: 50W Meridian: 6  
Latitude: 38.427871 Longitude: -103.017976

CORRECTIVE ACTIONS:

1 CA# 199325

Corrective Action: Comply with 1004 Rules Date:

Response: CA COMPLETED Date of Completion: 10/29/2024

Operator Comment: Had meeting w Tom Hoak at enforcement - We agree the native grasses have not taken hold. We asked that Chris Sanchez be asked to take a look and offer advise as to what we can do. Ripping and planting in the fall is not a viable solution. The area was ripped, contoured, planted and stabilized in summer or 2022. We have responsibility for a portion of this parcel and were surrounded by weeds. That's what grew. The project is

obviously incomplete however, we need some advise on how to get to an acceptable solution. OCRRECTIVE ACTION COMPLETE is the only way to respond to this . IT IS NOT COMPLETE!

ECMC Decision: \_\_\_\_\_

ECMC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: part of a 2 hour meeting w Tom Hoak at Enforcement. Spring activity with some add'l advise from ECMC experts.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Shawn Reed

Signed: \_\_\_\_\_

Title: Petroleum Consultant

Date: 11/6/2024 9:18:29 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files