

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403985767

Date Received:

11/06/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Costa, Ryan

ryan.costa@state.co.us

Harms, Jason

Jason@strachanexploration.com

L. Stacy

stacy@strachanexploration.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 710500377

Inspection Date: 09/24/2024

FIR Submit Date: 09/26/2024

FIR Status: _____

Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC

Company Number: 83130

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

LOCATION - Location ID: 321213

Location Name: BOURNE-622S48W Number: 30SENW County: _____

Qtrqtr: SENW Sec: 30 Twp: 22S Range: 48W Meridian: 6

Latitude: 38.108555 Longitude: -102.844724

FACILITY - API Number: 05-011- -00 Facility ID: 321213

Facility Name: BOURNE-622S48W Number: 30SENW

Qtrqtr: SENW Sec: 30 Twp: 22S Range: 48W Meridian: 6

Latitude: 38.108555 Longitude: -102.844724

CORRECTIVE ACTIONS:

1 CA# 199075

Corrective Action: Original corrective action Date shall apply

Date: 09/25/2024

Response: CA COMPLETED

Date of Completion: 09/25/2024

Operator
Comment: Sign Installed

ECMC Decision: _____

ECMC
Representative:

2 CA# 199076

Corrective Action: Install sign to comply with Rule 605.e

Date: 09/25/2024

Original Corrective action date shall apply

Response: CA COMPLETED

Date of Completion: 10/04/2024

Operator
Comment: Sign installed

ECMC Decision: _____

ECMC
Representative:

3 CA# 199077

Corrective Action: Dispose of contaminates soils in accordance with Rule 905. Operator shall provide waste manifest once contaminated soils are removed

Date: 10/30/2024

Response: CA COMPLETED

Date of Completion: 10/04/2024

Operator
Comment: Buckets of impacted soil delivered to Otero Landfill Manifest included in attachments - secondary containment removed from location

ECMC Decision: _____

ECMC
Representative:

4 CA# 199078

Corrective Action: Comply with Rule 606.

Date: 09/25/2024

Original CA date shall apply

Response: CA COMPLETED

Date of Completion: 09/25/2024

Operator
Comment: risers capped and marked

ECMC Decision: _____

ECMC
Representative:

5 CA# 199079

Corrective Action: Comply with 606.
Original Corrective action date shall apply

Date: 09/25/2024

Response: CA COMPLETED

Date of Completion: 09/25/2024

Operator
Comment: Weeds mowed on perimeter and the few inside the perimeter were also mowed. Rebuild of berm unnecessary as tank was removed under F27 for decommissioning.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Mowed, capped stubs, removed impacted soil, replaced sign w proper operator, Removed MEOH tank and secondary containment (stocktank)

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Shawn Reed

Signed: _____

Title: Petroleum Consultant

Date: 11/6/2024 10:22:00 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403985767	FIR RESOLUTION SUBMITTED
403985769	Manifest at Otero Landfill for impacted soil

Total Attach: 2 Files