

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2024

Submitted Date:

11/07/2024

Document Number:

717700641**FIELD INSPECTION FORM**Loc ID 458676 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10518Name of Operator: CONFLUENCE DJ LLCAddress: 1401 WYNKOOP STREET STE 120City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gale, Justin		jgale@confluencelp.com	All Inspections
,		dnr_cogccengineering@state.co.us	
Rothe, Brittany		brothe@confluencelp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458677	WELL	DG	03/04/2020	LO	123-48436	SILVERTON 5-6-1L	DG

General Comment:[This is an audit on the well.](#)

Location				
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type				
Comment:	No wellhead sign			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected FacilitiesFacility ID: 458677 Type: WELL API Number: 123-48436 Status: DG Insp. Status: DG**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: T/A, Surface Casing has been drilled. Form 5 was received on 4/23/2020
Confluence has suspended drilling operations in order to evaluate the economic viability
of horizontal development in this area prior to continuing the Silverton program. The
anticipated date of resumption of drilling is TBD pending the results of Confluence's
economic analysis. Confluence will comply with all bradenhead and MIT testing
requirements during the suspension of operations.

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: No updated annual BH test on file. 12/20/2024

Corrective Action: Submit reports as per Rule 419. Date: _____**Completion**

Operation: _____

Date Flowback: _____

Contractor: _____

Comment: _____

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
ECMC Inspection Report Summary On Tuesday, November 5, 2024, at approximately 10:47 AM, Inspector Adam Burns conducted an on-site inspection at the following location: Well: Silverton 5-6-1L Operator: Confluence DJ LLC API #05-123-48436 County: Weld During the inspection, a producing well was observed. The following possible compliance issues were identified: No updated annual BH test on file. Submit reports as per Rule 419. A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.	burnsa	11/07/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717700642	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6777851