

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403992322

Date Received:

11/13/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 12 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

.

COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 696205079

Inspection Date: 06/28/2023

FIR Submit Date: 07/06/2023

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 479149

Location Name: BJU Number: B26-496 Pad County: _____

Qtrqtr: NENW Sec: 26 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.677052 Longitude: -108.138400

FACILITY - API Number: 05-045- -00 Facility ID: 479149

Facility Name: BJU Number: B26-496 Pad

Qtrqtr: NENW Sec: 26 Twp: 4S Range: 96W Meridian: 6

Latitude: 39.677052 Longitude: -108.138400

CORRECTIVE ACTIONS:

12 CA# 174734

Corrective Action: Comply with Rule 908.c.

Date: 06/28/2023

- Submit a Form 15 for Cuttings Trench permitting requirements
- Submit a Form 27 for the cuttings remediation work completed to date.

The "Date of Discovery" is being provided as the corrective action date. Location will remain out of compliance until corrective action is resolved.

Response: CA COMPLETED

Date of Completion: 08/14/2024

This pad was permitted prior to the new rules taking effect and included the standard cuttings trench. Cuttings management area has been closed and approved.

ECMC
Representative:

Comment:

Signed:

Date: 11/13/2024 6:45:49 AM

403992322	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Page 2 of 2