

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404002328

Date Received:

11/21/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708303072

Inspection Date: 11/12/2024

FIR Submit Date: 11/15/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324126

Location Name: CHEVRON-66S96W Number: 20NWSE County: _____

Qtrqtr: NWSE Sec: 20 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.506358 Longitude: -108.130647

FACILITY - API Number: 05-045- -00 Facility ID: 324126

Facility Name: CHEVRON-66S96W Number: 20NWSE

Qtrqtr: NWSE Sec: 20 Twp: 6S Range: 96W Meridian: 6

Latitude: 39.506358 Longitude: -108.130647

CORRECTIVE ACTIONS:

1 CA# 200442

Corrective Action: Secure equipment to prevent wildlife entry.

Date: 11/20/2024

Response: CA COMPLETED

Date of Completion: 11/21/2024

Operator Comment: The vent line has an internal screen at top of the vent stack. No wildlife entry is possible. Corrective action completed.

ECMC Decision: _____

Date: 11/21/2024 10:54:51 AM

Total Attach: 1 Files