

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/13/2024

Submitted Date:

11/20/2024

Document Number:

713301251**FIELD INSPECTION FORM**Loc ID 318211 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections
Pesicka, Conor		conor.pesicka@state.co.us	
Silver, Randy	720-827-6688	randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240885	WELL	PR	08/01/2024	OW	123-08673	UPRR 43 PAN AM G 4	PR

General Comment:[follow up inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	safety guards		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	piped to surface		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	automation/electric panels		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:		
Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 240885 Type: WELL API Number: 123-08673 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: FLOWLINE AVAILABLE-CONNECTEDComment: Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.Date: 04/12/2024**BradenHead**Date of Last Brhd Test: 03/20/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0Comment: _____Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>ECMC Inspection Report Summary</u> <u>Inspector Michael Kester,</u> <u>conducted an on-site Follow up inspection as per doc# 713300679, in accordance with Rule 901a,</u> <u>corrective actions appeared to have NOT been addressed</u> <u>Location: UPRR 43 Pan Am G 4</u> <u>Operator: KPK</u> <u>API#: 123-08673</u> <u>County: Weld</u> <u>Mechanical integrity Testing, Rule 417b, corrective action date 4-12-2024</u> <u>Weather conditions: clear and dry</u> <u>This inspection does not nullify any orders or NOAV from the ECMC</u>	kesterm	11/13/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404002265	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6795107
713301252	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6795082