

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/17/2024

Submitted Date:

12/17/2024

Document Number:

697010574**FIELD INSPECTION FORM**Loc ID 319448 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	
,		cogccinspection@pdce.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434273	WELL	PR	06/01/2022	OW	123-38069	Five Rivers K18-69HN	PR

**General Comment:**

This is a routine audit. Any corrective actions from previous audits that have not been addressed are still applicable. There were no operator personnel on location at the time of this field audit.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign is not posted, see attached photo.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	03/21/2025

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Steel flood fencing and panel fencing		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Tank battery #481295				
Corrective Action:				Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		



Inspected Facilities									
Facility ID:	434273	Type:	WELL	API Number:	123-38069	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR							
Corrective Action:						Date:			
BradenHead									
Date of Last Brhd Test:		07/23/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		85		Fluid Type: WATER AND GAS			
		End Surf Csg Pressure:		0					
Comment:									
Corrective Action:						Date:			

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary</p> <p>On Tuesday 12/17/2024 at approximately 12:50 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDCE Five Rivers K 18-69 HN API #123-38069 in Weld County, Colorado.</p> <p>While there, I observed that the wellhead sign was not posted. During this inspection the following possible compliance issues were observed: Rule 605.d. with a corrective action date of 3/21/2025.</p> <p>A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	12/17/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697010575	Photo	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6829462">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6829462</a>