

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/15/2025

Submitted Date:

01/15/2025

Document Number:

714202026**FIELD INSPECTION FORM**Loc ID 311363 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Watzman, Ross		rwatzman@kpk.com	<a href="#">All Inspections</a>
Norton, Matthew		mnorton@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247274	WELL	SI	07/01/2024	GW	123-15071	MUSICK MCCLINTOCK 7	SI

**General Comment:**

This is an audit of MUSICK-McCLINTOCK #7 scout card and related documents followed by a field inspection.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No operator displayed on signage. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605	Date:	08/01/2024

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	dead, overgrown vegetation on various areas of location. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	08/01/2024
Type	UNUSED EQUIPMENT		
Comment:	unused equipment south of pumpjack. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	08/01/2024

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	247274	Type:	WELL	API Number:	123-15071	Status:	SI	Insp. Status:	SI

Idle Well

Purpose:

☒ Shut In

☐ Temporarily Abandoned

Reminder:

EQUIPMENT ONSITE

Comment:

SI; valves appear to be in the closed position.

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test:

03/26/2024

Annual Brhd Completed?

Yes

Last Brhd Test Results

Initial Surf Csg Pressure:

25

Fluid Type:

End Surf Csg Pressure:

0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p><b>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 714201815.</b>  All previous corrective actions assigned to this location have not been resolved. All previous corrective actions have been re-assigned to this location with their original corrective action date. No new corrective actions were observed at the time of re-inspection. Please review my findings below.</p> <p>ECMC Inspection Report Summary  <b>WEATHER CONDITIONS:</b> sunny, dry ground.  On Wednesday, January 15, 2025 at approximately 1130, I, Inspector Brittani Santistevan, conducted an on-site inspection at MUSICK-McCLINTOCK #7 (KP Kauffman Company, Inc), at location ID: 311363 in WELD COUNTY, Colorado.  While there, I observed a shut-in wellhead.  During this inspection the following possible compliance issues were observed:  1. It appears to be dead, overgrown vegetation on various areas of location. Comply with Rule 606. (Corrective Action Date: August 1, 2024) See attached photo #2-5.  2. It appears to be unused equipment south of pumpjack. Comply with Rule 606. (Corrective Action Date: August 1, 2024) See attached photo #2.  3. It appears the operator is no longer legible on pumpjack sign. Install sign to comply with Rule 605. (Corrective Action Date: August 1, 2024) See attached photo #1.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.  This is a summary of inspection report.</p>	santistb	01/15/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714202027	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6877750">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6877750</a>