



00054174

# LORADO OIL & GAS CONSERVATION COMMISSION

## FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- 121 - 07119		LEASE NAME: Simonson	
LOCATION: NESE 6 - 2N - 53W		OPERATOR: Tipps	
DATE: 10-10-95		INSPECTOR: Ed Binkley 8/24/65	
Insp. Type: SR	Insp. Status: DA	PA: Y <input checked="" type="radio"/> N	Pass/Fail: P <input checked="" type="radio"/> F
		Viol.: Y <input checked="" type="radio"/> N	NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)	Well plugged, Timbers onsite.	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)	35' x 6' deep pit prod. pit	
<b>Fences</b> (Rule 604.C.(3), 1003.A)	used while attempting to test well.	
<b>Tank Battery Equipment</b> (Rule 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 604)		
<b>General Housekeeping</b> (Rule 603.G)	(note: Robert Vaclavic called Mr. Tipps on 1-17-86 requesting P+A sundry.)	
<b>Spills (Oil/Water)</b> (Rule 908)	No form 10 issued at this time.	
<b>Bradenhead</b> (Rule 207)		
<b>Drilling Well/Workover</b> (Rule 315)		
<b>Surface Rehabilitation</b> (Rule 317)		
<b>Miscellaneous</b>	Appears to be a re-entry. (Tenant - Bob Armstrong ON SITE)	

**CORRECTIVE ACTION REQUIRED:** Close pit, remove boards and level location.

Date Corrective Action Required By: 10-30-95

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

Mailed 10-17-95