

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404064183

Date Received:

01/21/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

QB Energy

ecmc.inspections@qb-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708905509

Inspection Date: 01/18/2025

FIR Submit Date: 01/18/2025

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334945

Location Name: DUNN-67S92W Number: 4NENW County: _____

Qtrqtr: NENW Sec: 4 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.474370 Longitude: -107.673350

FACILITY - API Number: 05-045- -00 Facility ID: 334945

Facility Name: DUNN-67S92W Number: 4NENW

Qtrqtr: NENW Sec: 4 Twp: 7S Range: 92W Meridian: 6

Latitude: 39.474370 Longitude: -107.673350

CORRECTIVE ACTIONS:

1 CA# 201889

Corrective Action: Install or maintain liner material to ensure spill or released materials will be maintained with containment structure

Date: 03/27/2024

Response: CA COMPLETED

Date of Completion: 01/20/2025

Operator Comment: Repaired liner.

ECMC Decision: _____

Date: 01/25/2025

Date of Completion: 01/20/2025

Installed cap on flowline insulation.

ECMC Decision: _____

Comment:	Unable to upload photos due to webforms not populating a photo description after we type out the description in the popup, then select 'Update'. Called and spoke with Conor Pesicka and he said he didn't know what the issue would be. Of the several individuals from QB Energy that utilize webforms, we have all experienced this issue. If photos are needed, please reach out and we can send them direct to the inspectors.
----------	---

Signed:

Date: 1/21/2025 10:39:01 AM

404064183	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Page 2 of 2