

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404092874

Date Received:

02/13/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10840

Name of Operator: ABUNDANCE ENERGY SERVICES LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Price, Andrew

aprice@abundance-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001762

Inspection Date: 01/24/2025

FIR Submit Date: 01/30/2025

FIR Status: _____

Inspected Operator Information:

Company Name: ABUNDANCE ENERGY SERVICES LLC

Company Number: 10840

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 325099

Location Name: JACQUES-N33N8W Number: 27NWSE County: _____

Qtrqtr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.072690 Longitude: -107.700453

FACILITY - API Number: 05-067- -00 Facility ID: 325099

Facility Name: JACQUES-N33N8W Number: 27NWSE

Qtrqtr: NWSE Sec: 27 Twp: 33N Range: 8W Meridian: N

Latitude: 37.072690 Longitude: -107.700453

CORRECTIVE ACTIONS:

1 CA# 202208

Corrective Action: Comply with rule 406. install wildlife protections.

Date: 02/06/2025

Response: CA COMPLETED

Date of Completion: 02/06/2025

Operator Comment: Location signs were up-dated as soon as weather conditions would allow the stickers to adhere to the cold metal sign.

ECMC Decision: _____

Date:

Date of Completion: 02/06/2025

Wildlife cover has been installed over the cellar at well head.

Comment: See attachment for internal remedial report.

Signed:

Date: 2/13/2025 1:20:46 PM

404092874	FIR RESOLUTION SUBMITTED
404092928	Remedial Report

Page 2 of 2