

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2025

Submitted Date:

02/11/2025

Document Number:

713601872**FIELD INSPECTION FORM**

Loc ID 484357 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num:

Operator Information:ECMC Operator Number: 10797Name of Operator: DESERT EAGLE OPERATING LLCAddress: 17330 PRESTON RD STE 200D-208City: DALLAS State: TX Zip: 75252**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Sanchez, Chris		chris.sanchez@state.co.us	
Bulf, Cathy		cathybulf@gmail.com	
Butler, Brad		butleroil@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484674	WELL	PR	11/28/2023	HE	071-09928	Red Rocks 1-14	RI

General Comment:

This is a follow up inspection at the Red Rocks #1-14 wellsite.
See attached photos and additional details within this report.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign has been reinstalled at the wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	All equipment and containers have been removed. There were mulitple areas where equipment and/or containers had spilled fluid onto the surface. There are stained soils that have not been cleaned up since the previous inspection. Previous CA was not completed.		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention. Immediately clean up area. 24-48 hours to implement improved procedures. 1002.f.(2)B. Comply with permit BMP/COA's.		Date: <u>12/13/2024</u>

Overall Good: ☐

Spills:				
Type	Area	Volume		
	WELLHEAD			
Comment:	There was oil stained soils at the wellhead where the drilling rig was parked. The leak stained the soils approximately 40 ft. from the wellhead area. The stained soils still remain and have not been cleaned up. Previous CA was not completed.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Immediately clean up area. 24-48 hours to implement improved procedures. 1002.f.(2)B.			Date: <u>12/13/2024</u>

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Environmental					
Waste Management:					
Type	Management	Condition	GPS (Lat) (Long)		
Drill Cuttings		Inadequate			
Comment	There was red drill cuttings previously observed at the wellsite that had spilled onto the surface. During this inspection, there was still visible red and white drill cuttings that remain around the wellhead area. A form 19 and form 27 has been submitted for further investigation and remediation. Additional removal of spilled drill cuttings will need to be performed.				
Corrective Action					Date:
Spill/Remediation:					
Comment:					
Corrective Action:					Date:
Emission Control Burner (ECB):					
Comment:					
Pilot:	Wildlife Protection Devices (fired vessels):				

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____ Fail _____

Comment [Soils on the location are not being protected from contamination, compaction, or erosion.](#)

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Fail

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-CroplandTop soil replaced _____ Recontoured _____ 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Interim reclamation is not progressing at the location or along the flowline disturbance area. There was recent drilling activities performed at the location and soils are now compacted. The flowline disturbance has not established perennial vegetation. The disturbed soils need to be stabilized until vegetation establishes with the use of BMP's. All soil decompaction, reclamation, and stabilization will need to be completed before the upcoming growing season.

Corrective Action Comply with 1003 Rules.

Date _____

Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Inspector Name: COSTA, RYAN

Corrective Action: <input style="width: 600px;" type="text"/>					Date: <input style="width: 100px;" type="text"/>	
Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<div style="display: flex; justify-content: space-between;"><div>Comment: <div style="border: 1px solid black; padding: 5px; width: 80%;">The perimeter wattles at the wellsite have been reinstalled. There are still disturbed soils that are susceptible to erosion at the location and along the flowline disturbance area. Additional BMP's will be needed to prevent erosion.</div></div><div>Corrective Action: <input style="width: 550px;" type="text"/></div><div>Date: <input style="width: 100px;" type="text"/></div></div>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404089413	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6913915
713601873	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6913881