

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404008303

Date Received:

02/20/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302974

Inspection Date: 10/24/2024

FIR Submit Date: 10/28/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334884

Location Name: FEDERAL-67S96W Number: 4SENE County: _____

Qtrqtr: SENE Sec: 4 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.467629 Longitude: -108.106436

FACILITY - API Number: 05-045- -00 Facility ID: 334884

Facility Name: FEDERAL-67S96W Number: 4SENE

Qtrqtr: SENE Sec: 4 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.467629 Longitude: -108.106436

CORRECTIVE ACTIONS:

1 CA# 200131

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 10/19/2024

Response: CA COMPLETED

Date of Completion: 11/21/2024

Operator
Comment:

Rills have been repaired and the area has been stabilized to prevent future erosion. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: Rills have been repaired and the area has been stabilized to prevent future erosion. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 2/20/2025 12:34:43 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files