

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404011484

Date Received:

02/21/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302970

Inspection Date: 10/24/2024

FIR Submit Date: 10/25/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334896

Location Name: GM Number: 34-4 County: _____

Qtrqtr: SWSE Sec: 4 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.461755 Longitude: -108.110108

FACILITY - API Number: 05-045-00 Facility ID: 334896

Facility Name: GM Number: 34-4

Qtrqtr: SWSE Sec: 4 Twp: 7S Range: 96W Meridian: 6

Latitude: 39.461755 Longitude: -108.110108

CORRECTIVE ACTIONS:

1 CA# 200097

Corrective Action: Secure equipment to comply with Rule 608.e.

Date: 11/02/2024

Response: CA COMPLETED

Date of Completion: 11/21/2024

Operator Comment: Open ended lines have been plugged. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

2 CA# 200098

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 10/18/2024

Response: CA COMPLETED

Date of Completion: 11/21/2024

Operator
Comment:

Location and access road have been bladed/graded to remove rills and increase stabilization, Corrective Action complete.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #200097: Open ended lines have been plugged. Corrective Action complete.
CA #200098: Location and access road have been bladed/graded to remove rills and increase stabilization, Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 2/21/2025 4:57:11 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404011484	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files