

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404149706

Date Received:

04/02/2025

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 46685

Name of Operator: KINDER MORGAN CO2 CO LLC

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

General

CO2Source\_Regulatory@kindermorgan.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714002021

Inspection Date: 03/31/2025

FIR Submit Date: 04/01/2025

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LLC

Company Number: 46685

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

#### LOCATION - Location ID: 454942

Location Name: DC Number: 22 Pad County: \_\_\_\_\_

Qtrqtr: SESW Sec: 8 Twp: 40N Range: 17W Meridian: N

Latitude: 37.737199 Longitude: -108.751609

#### FACILITY - API Number: 05-033-00 Facility ID: 454942

Facility Name: DC Number: 22 Pad

Qtrqtr: SESW Sec: 8 Twp: 40N Range: 17W Meridian: N

Latitude: 37.737199 Longitude: -108.751609

### CORRECTIVE ACTIONS:

1 CA# 203806

Corrective Action: Comply with rule 1003, conduct interim reclamation on location. Location was previously failed for interim reclamation and required compliance by 5/15/2020. Original CA and date remains applicable. No CA date is being provided as this location is out of compliance for the same Rule.

Date: \_\_\_\_\_

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator Comment: Interim reclamation was performed in accordance with an Interim Reclamation Plan approved by BLM, the lead surface managing agency, on 2/17/2023 (attached, Sundry ID 2713747). A Sundry Subsequent Report of Reclamation was submitted upon completion of interim reclamation and approved by BLM on 8/7/2023 (attached,

Sundry ID 2743701). Per Page 6 of the "Memorandum of Understanding Between the Bureau of Land Management, Colorado State Office, and the Colorado Energy & Carbon Management Commission Concerning Federal Fluid Mineral Regulation in Colorado," BLM CO acts as the Lead Agency in Fed/Fed fluid mineral development scenarios concerning reclamation responsibilities (attached). A Form 45 Location Construction Report for completion of interim reclamation was submitted to ECMC on 8/1/2023 and is In Process by ECMC (attached, Doc #403461415).

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jenna Emerick

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 4/2/2025 7:57:55 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
404149706	FIR RESOLUTION SUBMITTED
404149716	ECMC Form 45 Construction Report
404149721	BLM Sundry Approved Int Rec Plan
404149723	BLM Sundry Approved Completion of Int Rec
404149725	MOU

Total Attach: 5 Files