

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404105725

Date Received:

04/09/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708303022

Inspection Date: 11/04/2024

FIR Submit Date: 11/05/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335168

Location Name: Federal Number: DOE 1-W-27 County: _____

Qtrqtr: Lot 6 Sec: 27 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.496523 Longitude: -107.989114

FACILITY - API Number: 05-045- -00 Facility ID: 335168

Facility Name: Federal Number: DOE 1-W-27

Qtrqtr: Lot 6 Sec: 27 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.496523 Longitude: -107.989114

CORRECTIVE ACTIONS:

1 CA# 200272

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 11/20/2024

Response: CA COMPLETED

Date of Completion: 12/16/2024

Operator Comment: 1 1/2" screened rock was used to stabilize the location. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: 1 1/2" screened rock was used to stabilize the location. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 4/9/2025 10:12:36 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

404105725	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files