

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404107536

Date Received:

04/09/2025

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708303490

Inspection Date: 02/23/2025

FIR Submit Date: 02/23/2025

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

#### LOCATION - Location ID: 334813

Location Name: Savage Number: GV 80-4 County: \_\_\_\_\_

Qtrqtr: NESW Sec: 4 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.463550 Longitude: -108.006923

#### FACILITY - API Number: 05-045-00 Facility ID: 334813

Facility Name: Savage Number: GV 80-4

Qtrqtr: NESW Sec: 4 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.463550 Longitude: -108.006923

### CORRECTIVE ACTIONS:

1 CA# 202635

Corrective Action: Repair fencing. 602.c: Operators are responsible for ensuring that operations are conducted with due regard for the safety of employees, for the preservation and conservation of property, and for protecting and minimizing adverse impacts to public health, safety, welfare, the environment, and wildlife resources.

Date: 03/03/2025

Response: CA COMPLETED

Date of Completion: 02/26/2025

Operator  
Comment:

Fence has been repaired. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 202636

Corrective Action: Replace signs to comply with Rule 605.d.

Date: 03/19/2025

Response: CA COMPLETED

Date of Completion: 03/18/2025

Operator  
Comment:

Wellhead signs have been replaced. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA #202635: Fence has been repaired. Corrective Action complete.  
CA #202636: Wellhead signs have been replaced. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 4/9/2025 12:37:49 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404107536	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files