

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404150907

Date Received:

04/18/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

White, Jeff

jeffery.white@chevron.com

rbucogccinspectionreports@chevron.onmicrosoft.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 713900744

Inspection Date: 07/02/2024

FIR Submit Date: 07/03/2024

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 329434

Location Name: SMITH-64N64W Number: 9SWNW County: _____

Qtrqtr: SWN Sec: 9 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.328686 Longitude: -104.562604

FACILITY - API Number: 05-123- -00 Facility ID: 329434

Facility Name: SMITH-64N64W Number: 9SWNW

Qtrqtr: SWN Sec: 9 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.328686 Longitude: -104.562604

CORRECTIVE ACTIONS:

1 CA# 196492

Corrective Action: The Operator has two compliance scenario options, in the case of continued use of the tank battery location the location will be continued to be stabilized and offsite sedimentation will be repaired and reclaimed as soon as environmentally possible based on crop harvest.

Date: _____

In the case of decommissioning of the tank battery location the entirety of the disturbance caused by the offsite sedimentation shall be included in Final Reclamation activities.

Response: CA COMPLETED

Date of Completion: 04/02/2025

Operator Comment: Chevron decommissioned the tank battery and performed reclamation activity to stabilize the area. A portion of the remedial activities have been completed after the equipment was removed. Right now the area has been prepped for farming season. We are to return in winter to finish remedial activity at Tank Battery.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Complied with stabilizing the footprint of the tank battery caused by the runoff from the overspray by the center pivot across the equipment on the former location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff White

Signed: _____

Title: HSE

Date: 4/18/2025 4:35:25 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

404150919	photos
-----------	--------

Total Attach: 1 Files