

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2025

Submitted Date:

05/07/2025

Document Number:

715501677

FIELD INSPECTION FORMLoc ID 313023 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 3975

Name of Operator: ARGALI EXPLORATION COMPANY

Address: PO BOX 416

City: RANGELY State: CO Zip: 81648

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		argaliexplorationcompany@gmail.com	
Rector, Jeff	(970) 629-2614	jbrduco@yahoo.com	
Rector, Brian	(970) 629-1906	brector1983@gmail.com	
Engineering, ECMC		dnr_cogccengineering@state.co.us	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Enforcement, ECMC		dnr_cogccenforcement@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223379	WELL	SI	10/01/2024	GW	081-06743	FEDERAL 7-25	SI

General Comment:

ECMC Inspection Report Summary

On Wednesday, 05/07/2025, Inspector Kirby Burchett, was on location for a follow up field inspection at Argali Exploration Company on the Federal 7-25 well, Location #313023, in Moffat County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority, NSO, Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #715500027 on 5/15/24. No response from operator. The following Corrective Actions are unresolved and original due dates remain:

1. No well sign.
2. Relief risers missing caps.

Refer to Inspection Photos for observed compliance issues.

While on location no additional compliance issues were observed.

** Review of production records indicate operator is delinquent in submitting monthly operations reports. **

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellhead sign not visible displayed. Stood back up against wellhead. 2nd time.		
Corrective Action:	Operators will ensure that signs are well maintained and legible, and will replace damaged or vandalized signs within 30 days of discovery that the sign is no longer legible or is damaged.	Date:	06/07/2025

Emergency Contact Number:

Comment:	(970) 629-1906	
Corrective Action:		Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead tree		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Relief riser caps missing.		
Corrective Action:	Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.	Date:	05/31/2024
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Inspected Facilities									
Facility ID:	223379	Type:	WELL	API Number:	081-06743	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>December 2024 Production Report Shut In - October 2024 Review of production records indicate operator is delinquent in submitting monthly operations reports.</div>									
Corrective Action: <div>Operators will report all existing oil and gas Wells that are not Plugged and Abandoned on the Form 7, Operator's Monthly Report of Operations within 45 days after the end of each month.</div>									
Date: 06/07/2025									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Ditches						

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501678	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7039391