



PHOTO 1: THE STAINED SOIL NEAR THE ROAD HAS BEEN REMOVED AND REPLACED WITH FRESH PAD MATERIAL.



AC COMPRESSOR 2 – OGRIS OPERATING  
COGCC OPERATOR NUMBER 10758 - DATE: MAY 14, 2025  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #713602117



PHOTO 2: THE LEAK HAS BEEN CONTROLLED AT THE TANK. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.