

Operator: HIGHPOINT OPERATING CORPORATION

Location Name: Bolin 6-62-13_24 NWNW

Loc ID: 423426

Inspection: 708201803

CA: It appears that Location ID (423426) was expanded for Well API (123-44400, 123-44395 and 123-44399) with historical aerial imagery showing evidence of a drilling pad and access road construction. The AL wells were never drilled and the Operator submitted Form 4 Sundry Notices abandoning the well permits. The former drilling pad appears to have been reclaimed, however, the access road off of WCR 85 does not appear to have been reclaimed as evidenced by contouring/grading issues and road base material. Additional reclamation activities are required to reclaim the access road. Refer to attached inspection photos for additional information. Perform reclamation in accordance to Rule 1003. Reclaim access roads and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

CA Resolution: Operator has reclaimed the access road in compliance with Rule 1003.



Exhibit 1



Exhibit 2