

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404211825

Date Received:

05/21/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10412

Name of Operator: AUSCO PETROLEUM INC

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

HART, TIMOTHY B

thart@fremontpetroleum.com

HARKINS, LIZ

lharkins@austinexploration.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 690201452

Inspection Date: 04/22/2021

FIR Submit Date: 04/26/2021

FIR Status: _____

Inspected Operator Information:

Company Name: AUSCO PETROLEUM INC

Company Number: 10412

Address: 113 N SANTA FE AVENUE

City: FLORENCE State: CO Zip: 81226

LOCATION - Location ID: 429093

Location Name: Pathfinder Number: C 11-12 1 County: FREMONT

Qtrqtr: NWN Sec: 12 Twp: 20S Range: 70W Meridian: 6

Latitude: 38.328850 Longitude: -105.178654

FACILITY - API Number: 05-043-00 Facility ID: 430103

Facility Name: Pathfinder Number: 2

Qtrqtr: NWN Sec: 12 Twp: 20S Range: 70W Meridian: 6

Latitude: 38.328850 Longitude: -105.178654

CORRECTIVE ACTIONS:

1 CA# 150070

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 04/30/2021

Response: CA COMPLETED

Date of Completion: 03/05/2025

All valves, pipes, and fittings were tightened to ensure good mechanical condition. Spilled material was cleaned up. ECMC Inspection Doc No.716300650, conducted on March 5, 2025, confirmed CA had been conducted.

Operator
Comment:

ECMC Decision:

ECMC
Representative:

2 CA# 150071

Corrective Action: Comply with the fencing requirements per the 1002a rules

Date: 02/18/2021

Response: CA COMPLETED

Date of Completion: 03/15/2024

Operator
Comment:

Fence maintenance conducted. ECMC Inspection Doc number 690202697, conducted on March 15, 2024, confirmed CA had been completed.

ECMC Decision:

ECMC
Representative:

3 CA# 150072

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/11/2020

Response: CA COMPLETED

Date of Completion: 03/15/2022

Operator
Comment:

Stormwater erosion occurring down the access road and into the drainage area was fixed. BMP's were implemented in accordance with good engineering practice. ECMC Inspection Doc No. 690202697, conducted on March 15, 2022, confirmed completion of CA.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mackenzie Smith

Signed:

Title: Staff Engineer

Date: 5/21/2025 9:30:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404211825	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files