

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404219510

Date Received:

05/28/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

505-324-5188

pshorty@hilcorp.com

.General

FarmingtonRegulatoryTechs@hilcorp.com

Walker, Mandi

mwalker@hilcorp.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714002178

Inspection Date: 05/13/2025

FIR Submit Date: 05/20/2025

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 333826

Location Name: ARGENTA 33-10-N33N10W Number: 4SENE County: \_\_\_\_\_

Qtrqtr: SENE Sec: 4 Twp: 33N Range: 10W Meridian: N

Latitude: 37.135490 Longitude: -107.933640

FACILITY - API Number: 05-067- -00 Facility ID: 333826

Facility Name: ARGENTA 33-10-N33N10W Number: 4SENE

Qtrqtr: SENE Sec: 4 Twp: 33N Range: 10W Meridian: N

Latitude: 37.135490 Longitude: -107.933640

CORRECTIVE ACTIONS:

1 CA# 204956

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 1002.

Date: 05/27/2025

Response: CA COMPLETED

Date of Completion: 05/27/2025

Operator Comment: Leaks have been repaired and impacted material has been removed from location and disposed of properly. See attached photos.

ECMC Decision:			
ECMC Representative:			
<b>2</b> CA# 204957			
Corrective Action:	Comply with rule 1002f.	Date:	05/27/2025
Response:	CA COMPLETED	Date of Completion:	05/27/2025
Operator Comment:	Rutting and damaged culvert have been repaired properly. See attached photos.		
ECMC Decision:			
ECMC Representative:			

<b><u>OPERATOR COMMENT AND SUBMITTAL</u></b>	
Comment:	
<p>I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.</p> <p>Print Name: <u>Priscilla Shorty</u>      Signed: _____</p> <p>Title: <u>OperationsRegulatory Tech</u>      Date: <u>5/28/2025 9:54:10 AM</u></p>	

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404219510	FIR RESOLUTION SUBMITTED
404219513	Argenta 33-10 4-3_714202178 Resolved Photos

Total Attach: 2 Files