

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2025

Submitted Date:

05/28/2025

Document Number:

710500525**FIELD INSPECTION FORM**Loc ID 484359 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10797Name of Operator: DESERT EAGLE OPERATING LLCAddress: 17330 PRESTON RD STE 200D-208City: DALLAS State: TX Zip: 75252**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Bulf, Cathy		cathybulf@gmail.com	Desert Eagle Operating llc
Butler, Brad	972-345-9195	butleroil@yahoo.com	Desert Eagle Operating llc
Costa, Ryan		ryan.costa@state.co.us	
Chaivre, Annie		annie.chaivre@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
484676	WELL	PR	01/18/2024	HE	071-09930	Red Rocks 35-08	EI

General Comment:

This is an Environmental Inspection for the Red Rocks 35-08, well location located in Las Animas County, Colorado. Remediation Project 32957

Location

Lease Road:			
Type			
comment:	Gravel road through rangeland		
Corrective ActionL		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well placard located at wellhead		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	At the time of inspection, unused poly pipe observed at the intersection of the county road and location access road. Comply with Rule 606.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stormwater BPMs/Wattles need maintenance		
Corrective Action:	Comply with Rule 1002.f.(2)C	Date:	06/18/2025
Type	WEEDS		
Comment:	At the time of inspection, noxious weeds and undesirable plant species were observed on the location and along the access road.		
Corrective Action:	Comply with Rule 1003.f.	Date:	06/13/2025

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	484676	Type:	WELL	API Number:	071-09930	Status:	PR	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spill/Remediation:**

Comment:

This is an Environmental Inspection for Remediation Project # 32957. At the time of inspection, the location had recently been ripped for reclamation purposes. Per Analytical data provided in Form 27 Document # 404113480 additional information is needed for soil suitability thresholds for available boron based on hot water soluble (or DPTA/sorbitol) extraction followed by analysis.

In addition, analytical data for chromium appears to be for total chromium. Per Table 915-1 Analytical Data is required for chromium (VI).

The Operator shall continue quarterly reporting until Full Table 915-1 standards are met within the remediation area.

Corrective
Action:

Continue quarterly reporting in accordance with Rule 913.e.

Date: 06/19/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500526	Location Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7068594