

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2025

Submitted Date:

06/13/2025

Document Number:

713302139

FIELD INSPECTION FORMLoc ID 319676 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Medina, Justin		justin.medina@state.co.us	
, KPK	303-825-4822	cogcc@kpk.com	all inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
200837	WELL	PR	09/01/2024	GW	001-06240	HOSMER HAROLD W. 1	PR

General Comment:[well site and facility inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	good		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	FADED		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	dead overgrown vegetation and new season of growth		
Corrective Action:	Comply with Rule 606	Date:	07/14/2025

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:	pipe panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	metal rod		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	metal rod		
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	automation		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV CONCRETE		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	50 Bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	shared with crude tanks				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					

Inspected FacilitiesFacility ID: 200837 Type: WELL API Number: 001-06240 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: Valves appeared to be closed at time of inspectionCorrective Action: Date: **BradenHead**Date of Last Brhd Test: 04/16/2025Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Inspector Michael Kester, did audit scout card and related documents conducted an on-site inspection, Location: Hosmer Harold 1 Operator: KPK API#: 001-06240 County: Adams While there, I observed well site with production equipment. During this inspection the following possible compliance issues were observed: Overgrown vegetation, Rule 606 corrective action date 7-14-2025 all photos Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC	kestern	06/13/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302140	site pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7095390