

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2025

Submitted Date:

06/12/2025

Document Number:

710500554

FIELD INSPECTION FORMLoc ID _____ Inspector Name: _____ On-Site Inspection ☐
Sanchez, Chris 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 17180

Name of Operator: CITATION OIL & GAS CORP

Address: 14077 CUTTEN RD

City: HOUSTON State: TX Zip: 77069

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Redweik, Bob	(281) 891-1550	bredweik@cogc.com	COGC
Kennedy, Herschel	719-767-8851	hkennedy@cogc.com	COGC
Longworth, Mike		mike.longworth@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
255941	GAS COMPRESSO R STATION	AC			-	Bledsoe Unit Press Maint Facility	EI
489278	SPILL OR RELEASE	AC	03/11/2025		-	Bledsoe Unit Press Maint Facility	EI

General Comment:

This is an Environmental Inspection for the Bledsoe Unit Press Maint Facility Located in Cheyenne County, Colorado. Spill ID 489278

Inspected Facilities									
Facility ID:	255941	Type:	GAS	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	489278	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spill/Remediation:**

Comment:

This is an Environmental Inspection for Spill ID 489278, Spill ID discovery Date 2/10/2025. At the time of inspection Spill ID 489278 was 23-days beyond the 90-day closure window per Rule 912.b.(6). The Operator shall file a Form 27-i for ongoing spill remediation in accordance with Rule 912.b.(6).

At the time of inspection, an open excavation was present at the spill site. The Operator shall continue spill investigation/remediation until the site meets Table 915-1 standards.

In addition, Operator shall manage the open excavation in accordance with Rule 913.b.(5)

Corrective Action:

Comply with Rule 912.b(6). and Rule 913.b.(5)

Date: 06/26/2025

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

ECMC Comments

Comment

User

Date

All previously assigned COAs and CAs shall apply

sanchezcc

06/12/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404239034	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093358
710500556	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093351