

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/11/2025

Submitted Date:

06/12/2025

Document Number:

717701468

FIELD INSPECTION FORM

Loc ID 336149 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241903	WELL	PR	08/01/2019	GW	123-09694	FIRESTONE 'B' 1	PR

General Comment:

[This is a routine well audit](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:		Date:	_____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil next to the pumping unit needs to be removed.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	07/04/2025

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Chainlink		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Chainlink		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241903 Type: WELL API Number: 123-09694 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/12/2024 Annual Brhd Completed? _____
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: BH annual test will need to be performed
 Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>On Wednesday, June 11, 2025, at approximately 11:02 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Well: Firestone 'B' 1 Operator: KP Kauffman Company Inc. API #05-123-09694 County: Weld</p> <p>During the inspection, the following possible compliance issues were identified: Stained Soil: Stained soil next to the pumping unit needs to be removed. "Properly dispose of oily waste in accordance with 905.e." CA date of 7/4/25</p> <p>A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.</p>	burnsa	06/12/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404238931	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093243
717701469	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7093236