



**RAT Observation**

- No Observed Source Material (9)
- Possible Source Material (0)
- Source Material Observed (0)





T230 RES - DILLARD KYLE - 24806 PLEASANT HILL AVE WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

**Observation**

Oiling Observation: **0 No Observable Oil** | Id: 549022 | 5/12/2025 12:52:18 PM  
(40.520779, -104.586195)  
Heating oil. No obvious presence of hydrocarbons. Tank right next to the house.





T230 RES - DILLARD KYLE - 24806 PLEASANT HILL AVE WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 549036 | 5/12/2025 1:11:17 PM  
(40.520766, -104.58591)

South of house Bay windows no obvious presence of hydrocarbons. Picking up a lot of dust.





**T230 RES - DILLARD KYLE - 24806 PLEASANT HILL AVE WELD**  
**Photo Log | Rapid Assessment Technique (RAT)**

**Incident** Bishop LOC  
**Incident Date** April 7, 2025  
**City** Galeton, CO  
**County** Weld

Oiling Observation: 0 No Observable Oil | Id: 549034 | 5/12/2025 1:12:36 PM  
(40.520802, -104.585996)

East side of house. Two windows and a door with no stairway. No obvious presence of hydrocarbon.





T230 RES - DILLARD KYLE - 24806 PLEASANT HILL AVE WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 549026 | 5/12/2025 1:15:59 PM  
(40.520889, -104.586096)

North side of the house windows continued. No obvious presence of hydrocarbons.





T230 RES - DILLARD KYLE - 24806 PLEASANT HILL AVE WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 549028 | 5/12/2025 1:17:16 PM  
(40.520831, -104.586242)

West side of living quarters. Main entrance. No obvious presence of hydrocarbons.





**T230 RES - DILLARD KYLE - 24806 PLEASANT HILL AVE WELD**  
**Photo Log | Rapid Assessment Technique (RAT)**

**Incident** Bishop LOC  
**Incident Date** April 7, 2025  
**City** Galeton, CO  
**County** Weld

Oiling Observation: 0 No Observable Oil | Id: 549029 | 5/12/2025 1:18:54 PM  
(40.520803, -104.586279)  
Building west of living quarters. No obvious presence of hydrocarbons.





T230 RES - DILLARD KYLE - 24806 PLEASANT HILL AVE WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 549038 | 5/12/2025 1:20:29 PM  
(40.520793, -104.586301)

Mazda SUV. No obvious presence of hydrocarbons. A lot of dust on the windows





T230 RES - DILLARD KYLE - 24806 PLEASANT HILL AVE WELD  
Photo Log | Rapid Assessment Technique (RAT)

Incident Bishop LOC  
Incident Date April 7, 2025  
City Galeton, CO  
County Weld

Oiling Observation: 0 No Observable Oil | Id: 549037 | 5/12/2025 1:21:27 PM  
(40.52088, -104.586255)  
Vehicle. Audi. No obvious presence of hydrocarbons.



Oiling Observation: 0 No Observable Oil | Id: 549027 | 5/12/2025 1:24:29 PM  
(40.520948, -104.586056)

Flower planters. Vegetable planters. No obvious presence of hydrocarbons. West of living quarters.

