

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/12/2025

Submitted Date:

06/30/2025

Document Number:

718200051

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: Metz, Collin On-Site Inspection
 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Anderson, Laurel		laurel.anderson@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
248518	WELL	PA		OW	123-16316	LDS WHITE D 19-15	EI
489269	SPILL OR RELEASE	AC	02/11/2025		-	LDS White D #19-15	EI

General Comment:

ECMC Environmental Field Inspection Report Summary

This is an environmental inspection to determine progress on Spill ID 489269 and Remediation Project #30826. Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 489269

Spill Name: LDS White D #19-15

Remediation Project #: 30826

Well API: 05-123-16316

Reported Date of Discovery: 02/07/2025

Date of Inspection: 06/12/2025

Weather Conditions: Sunny/Breezy 85-90 F

Spills are located within or adjacent to:

-Multiple jurisdictional wetlands

Current Site Status:

-Backfilled and interim reclamation started

See attached corrective actions. A Form 19 - Supplemental is required.

Inspected Facilities

Facility ID: 248518 Type: WELL API Number: 123-16316 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 489269 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: A historical release was discovered on 02/07/2025 during Remediation Project 30826 and the Form 19 Initial with Supplemental Report (Doc # 404087102) was received on 02/10/2025. Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure that was due 05/08/2025 and is 49 days late. Operator shall submit and request closure of the Form 19 by checking the box for "Work proceeding under an approved Form 27 (Rule 912.c)" for this project within 14 days. Operator is out of compliance with Rule 913.e.(3).

Corrective Action: Operator shall submit delinquent form for this project. Date: 07/14/2025

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404262147	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7121917
718200052	Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7121914