

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2025

Submitted Date:

07/02/2025

Document Number:

717900245**FIELD INSPECTION FORM**Loc ID 330074 Inspector Name: Robinson, Taylor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		rwatzman@kpk.com	
		cogcc@kpk.com	<a href="#">All Inspections</a>
		kari.l.brown@state.co.us	
		nikki.graber@state.co.us	

**General Comment:**

This is an environmental inspection for Location ID 330074 Lost Creek Tank Battery. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: Site is inundated with weeds. Operator to remove. This has been an ongoing CA that has yet to be addressed by KPK.

Corrective Action: Comply wiith rule 606.

Date: 07/16/2025

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment: No spills observed during the inspection.

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
Comment:						
Corrective Action:						Date:

**Paint**

Condition

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: Earthen berms surrounding both the above ground storage tanks and the separators are degraded and need to be re-built and recontoured to be fully functional in the event of a leak or spill. This has been an ongoing issue at this site that has yet to be addressed by KPK.					
Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).					Date: 07/16/2025

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:

Date:

**Location Construction**

Location ID: 330074

CDP: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Form 2A COAs:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Wildlife BMPs:**

Comment:

KPK has addressed the dead wildlife observed during the last inspection. KPK has also covered the open holes in the metal meshing on the two produced water vaults. However, ECMC notes that the cover used is nylon meshing that could potentially cause harm to wildlife if they were to become entangled in the new mesh. ECMC recommends a more permanent solution that does not potentially endanger wildlife.

Corrective Action:

Date: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

**Environmental****Spills/Releases:**

Type of Spill: _____	Estimated Spill Volume: _____
Comment: <u>No spills or releases were observed during the inspection.</u>	
Corrective Action: _____	Date: _____
Reportable: _____	GPS: Lat _____ Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____

**Water Well Complaint:**

		Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

**Field Parameters:**

Sample Location: _____	Comment: _____
------------------------	----------------

**ECMC Comments**

Comment	User	Date
<u>An NOAV citation has been issued for the wildlife mortality at this location.</u>	robinsotl	07/02/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717900246	photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7134452">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7134452</a>