

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2025

Submitted Date:

07/09/2025

Document Number:

718800466**FIELD INSPECTION FORM**Loc ID 317035 Inspector Name: Mitchem, Katelyn On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 24500Name of Operator: PADCO LLCAddress: 16508 ARMINTA STREETCity: VAN NUYS State: CA Zip: 91406**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		abrotherton@136elcamino.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234730	WELL	PA	12/10/2014	OW	121-06867	UNITED STATES COLORADO 2-A	RI
317035	LOCATION	AC	07/20/2020		-	UNITED STATES COLORADO-62N53W 33SWNW	RI

**General Comment:**

This is a final reclamation inspection at PA Well API# 121-06867 and its associated tank battery. The well was plugged and abandoned on 09/30/2014.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

Type:	#		corrective date
Comment:		No visual evidence of oil and gas equipment at the location. Refer to the attached inspection photos.	
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	234730	Type:	WELL	API Number:	121-06867	Status:	PA	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	317035	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental			
<b>Spills/Releases:</b>			
Type of Spill: _____		Estimated Spill Volume: _____	
Comment: <div>ECMC confirms that all remediation projects are approved and closed.</div>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____	Depth to Ground Water: _____		
<b>Water Well Complaint:</b>			
		Lat	Long
DWR Receipt Num: _____	Owner Name: _____	GPS :	_____
<b>Field Parameters:</b>			
Sample Location: _____		Comment: _____	

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage \_\_\_\_\_

Weeds present **Fail** Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% 58

TRANSECT RESULTS OF REFERENCE AREA% 94

TOTAL % OF DESIRABLE VEGETATION COVER 62

VEGETATIVE COVER FAIL

Comment: **The location does not meet reclamation regulations as vegetation has not established to Rule 1004 standards and weedy annual vegetation was observed across the location. The access road remains in place per the approved variance request.**

Corrective Action: **Comply with Rule 1004 to perform additional reclamation activities at the well and tank battery locations and perform weed management.**

Date \_\_\_\_\_

Overall Final Reclamation	<b>Fail</b>	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>			
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<div style="display: flex; justify-content: space-between;"><div>Comment: <span style="color: blue;">At the time of this inspection, no stormwater erosion issues were observed at the location or along the access road.</span></div><div>Date: _____</div></div> <div style="display: flex; justify-content: space-between;"><div>Corrective Action: <input style="width: 60%;" type="text"/></div><div>Date: _____</div></div> <div>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</div>						

ECMC Comments		
Comment	User	Date
The Location received an approved 502.b SOVR (Order No. 1-374, see corrected) to waive final reclamation requirements on the access road only per Rules 1004.a., 1004.c.(2), 1004.d., and 1004.e. Pursuant to Rule 1004.c.(4), Operator shall submit a Final reclamation completion notice, Form 4, once Location has met ECMC 1004 standards. Operator remains responsible for management of the Location and access road, including Stormwater Management pursuant to Rule 1002.f., until site receives a passing Final Reclamation inspection.	mitchemk	07/03/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404272689	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7134075">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7134075</a>
718800467	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7134063">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7134063</a>