

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2025

Submitted Date:

07/18/2025

Document Number:

713400920**FIELD INSPECTION FORM**

Loc ID 316285	Inspector Name: Popejoy, Dusty	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 12 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: <u>10539</u> Name of Operator: <u>UTAH GAS OP LTD DBA UTAH GAS CORP</u> Address: <u>734 MAIN STREET 3RD FLOOR</u> City: <u>GRAND JUNCTION</u> State: <u>CO</u> Zip: <u>81501</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
GAS, UTAH		inspections@utahgascorp.com	
Koch, Benjamin		bzkoch@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260507	WELL	PR	06/01/2024	GW	103-10150	FOUNDATION CREEK 7424	PR

General Comment:

[CECMC Inspection/Audit Report Summary](#)

On 07/15/2025 at approximately 12:13 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP FOUNDATION CREEK 7424 PAD at Location ID # 316285 in Rio Blanco County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Signs/Marker - Wellhead sign lacks required information/not in compliance with CECMC rules with a CA date of 08/18/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellhead sign lacks required information/not in compliance with CECMC rules		
Corrective Action:	Comply with CECMC Signage rules	Date:	08/18/2025
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-693-6021/911

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 2	
Comment:	Flameless gas infrared catalytic heater	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		,
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	260507	Type:	WELL	API Number:	103-10150	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Compaction						
		Compaction				
		Ditches				
		Culverts				
		Gravel				Sparse
Berms						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Signs/Marker for corrective actions.	popejoyd	07/18/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400921	713400920 Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7148755