

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2025

Submitted Date:

07/18/2025

Document Number:

713400922

FIELD INSPECTION FORM

 Loc ID: 315141
 Inspector Name: Popejoy, Dusty
 On-Site Inspection:
 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 10539
 Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
 Address: 734 MAIN STREET 3RD FLOOR
 City: GRAND JUNCTION State: CO Zip: 81501
Findings:

- 16 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Toews, Wesley		wtoews@blm.gov	
Katz, Aaron		aaron.katz@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Koch, Benjamin		bzkoch@blm.gov	
GAS, UTAH		inspections@utahgascorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230321	WELL	PR	06/01/2024	GW	103-07981	SOUTH DOUGLAS CREEK 7314	PR

General Comment:[CECMC Inspection/Audit Report Summary](#)

On 07/15/2025 at approximately 13:37 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP SOUTH DOUGLAS CREEK 7314 PAD at Location ID #315141 in Rio Blanco County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

- Equipment - Hole in separator building & separator heater open to wildlife/available for entry by wildlife with a CA date of 07/25/2025
- Stormwater - Subsidence on SE side of location, additionally is a wildlife hazard/personnel safety hazard with a CA date of 07/25/2025
- Signs/Marker - Wellhead sign lacks required information/not in compliance with CECMC rules with a CA date of 08/18/2025
- Inspected Facilities - Well lacks wellbore diagram/not in compliance with CECMC rules with a CA date of 08/18/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location			
Lease Road:			
Type	Access		
comment:	Access		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead sign lacks required information/not in compliance with CECMC rules		
Corrective Action:	Comply with CECMC Signage rules		Date: 08/18/2025
Type	OTHER		
Comment:	Sign at meter house		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-693-6021/911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris on location		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:			Date:
Equipment:			
Type: Bird Protectors	# 3		corrective date
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Hole in separator building & separator heater open to wildlife/available for entry by wildlife		
Corrective Action:	Comply with CECMC wildlife rules	Date:	07/25/2025
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	30 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 230321 Type: WELL API Number: 103-07981 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well on plunger lift

Well lacks wellbore diagram/not in compliance with CECMC rules

Corrective Action: Comply with CECMC Rule 420 & submit wellbore diagrams via FORM 4 SUNDRY or FORM 17

Date: 08/18/2025

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Ditches						
		Compaction				Light compaction
Other	Fail					Subsidence on SE side of location
Compaction						Light compaction
		Berms				

Comment: [1. Subsidence on SE side of location, additionally is a wildlife hazard/personnel safety hazard](#)

Corrective Action: [Comply with CECMC Storm water rules](#)

Date: 07/25/2025

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment, Stormwater, Signs/Marker & Inspected Facilities for corrective actions and Housekeeping for comments.	popejoyd	07/18/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400923	713400922 Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7149516