

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404291319

Date Received:

07/23/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302389

Inspection Date: 06/27/2024

FIR Submit Date: 07/08/2024

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335626

Location Name: MOBIL ALLEN POINT-  
66S95W

Number: 9NWSE

County: \_\_\_\_\_

Qtrqr: NWSE Sec: 9 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.536857 Longitude: -108.000501

FACILITY - API Number: 05-045- -00

Facility ID: 335626

Facility Name: MOBIL ALLEN POINT-  
66S95W

Number: 9NWSE

Qtrqr: NWSE Sec: 9 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.536857 Longitude: -108.000501

CORRECTIVE ACTIONS:

1 CA# 196557

Corrective Action: Secure load line to comply with Rule 608.e.

Date: 07/13/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Load line has been plugged. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC Representative:			
----------------------	--	--	--

<b>2</b>	<b>CA# 196558</b>		
Corrective Action:		Remove unused equipment from location.	Date: 07/15/2024
Response:		CA COMPLETED	Date of Completion: 10/17/2024
Operator Comment:		Hoses have been removed from the location. Corrective Action complete.	
ECMC Decision: _____			
ECMC Representative:			

<b>3</b>	<b>CA# 196559</b>		
Corrective Action:		Remove stored equipment from location.	Date: 07/15/2024
Response:		CA COMPLETED	Date of Completion: 10/17/2024
Operator Comment:		Unused steel pipe has been removed. Corrective Action complete.	
ECMC Decision: _____			
ECMC Representative:			

<b>4</b>	<b>CA# 196560</b>		
Corrective Action:		Secure hoses to comply with Rule 608.e.	Date: 07/13/2024
Response:		CA COMPLETED	Date of Completion: 10/17/2024
Operator Comment:		Hoses have been plugged. Corrective Action complete.	
ECMC Decision: _____			
ECMC Representative:			

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	CA #196557: Load line has been plugged. Corrective Action complete. CA #196558: Hoses have been removed from the location. Corrective Action complete. CA #196559: Unused steel pipe has been removed. Corrective Action complete. CA #196560: Hoses have been plugged. Corrective Action complete.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Jordan Veith	Signed: _____
Title: TEP Representative	Date: 7/23/2025 1:37:29 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files