

182534

Sahio Pet

1

PTA

12. 25

FORM 2013 R-2

CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		DESCRIPTION OF OPERATION AND MATERIALS
				T	C	TUBING	CASING	
								RECEIVED
	1000							Called Out JAN 23 1981
	1200							On Loc. 3010. CH. & CAS CONS. COMM.
	1205							Safety Meet.
	1345							Howco + Cust. Ready
	1350	8	20	1	2	2000		Run Spacer 1st plug H ₂ O
	1400	8	4	1	2	2000		Mix Cnt.
	1415	4	26	1		750		Displace cnt.
	1630	8	10	1		600		Run Spacer 2nd plug H ₂ O
	1635	8	21	1		600		Mix Cnt.
	1645	4	5.5	1		200		Displace cnt.
	1700	8	5	1		200		Run Spacer 3rd plug H ₂ O
	1715	8	10	1		200		Mix Cnt.
	1730	1	.5	1		50		Disp. Cnt.
	1740							Dump 10 sk. for top of surf.
	1745							Wash pump + lines
	1745							Job Complete (Trks. + Crew Released) Thank You

1957-1958

CUSTOMER