

Inspection Photos
Location Name: Saulcy 4-1
API: 05-123-10770

NW¼ NE¼ Section 4 Township 4 North Range 68 West



Photo 1: View at terminal location of released liquid migration in ditch along Highway 60. Berm built in ditch on dowgradient, west end of release. Photo views to North.



Photo 2: View at terminal end of released liquid migration, viewing east along Highway 60.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Saulcy 4-1
API: 05-123-10770

NW¼ NE¼ Section 4 Township 4 North Range 68 West



Photo 3: View at access point on driveway from Highway 60. Viewing release liquid migration path along east side of driveway. Photo is viewing south toward release location.



Photo 4: View at release location where liquids migrated into ditch along driveway. Berm constructed in driveway ditch to contain release liquid. Photo is viewing southeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Saulcy 4-1
API: 05-123-10770

NW¼ NE¼ Section 4 Township 4 North Range 68 West



Photo 5: View from driveway to northeast at release point. Apparent release point and well location is orange flagging on stake in upper right of photo.



Photo 6: View where release liquid enters ditch along driveway. Photo is viewing to north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Saulcy 4-1
API: 05-123-10770
NW¼ NE¼ Section 4 Township 4 North Range 68 West



Photo 7: Panaramic view of release area. Apparent release point is orange flagging in left of photo. Photo is viewing west toward driveway.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources