


# Location Drawing Wildfire 41-10

NO VISIBLE IMPROVEMENTS FOUND WITHIN 400FT OF PROPOSED WELL LOCATION




SURFACE USE: **TIMBER**

**NOTE:**

FOOTAGES GIVEN ARE ONLY ESTIMATES BASED ON SUBDIVISION PLATS AND TIED TO EXISTING CONTROL. A FULL BOUNDARY SURVEY IS REQUIRED TO DETERMINE TRUE SUBDIVISION LOT AND ROAD LOCATIONS, DISTANCES AND AREA OR FOOTAGE CALCULATIONS.

DATE: October 15, 2009

### GRAPHIC SCALE



**SHIELDS SURVEY Ltd. Co.**  
Raton, New Mexico 87740  
(575)445-1232