

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303)894-2100 Fax:(303)894-2109



FOR OGCC USE ONLY

## SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and

Spill report taken by:

FACILITY ID:

### OPERATOR INFORMATION

Name of Operator: <u>Petroleum Development Corporation (PDC)</u> OGCC Operator No: <u>69175</u>	Phone Numbers
Address: <u>1775 Sherman Street, Suite 3000</u>	No: <u>(303) 860-5800</u>
City: <u>Denver</u> State: <u>CO</u> Zip: <u>80203</u>	Fax: <u>(970) 860-5838</u>
Contact Person: <u>Randall Ferguson</u>	Email: <u>rferguson@petd.com</u>

### DESCRIPTION OF SPILL OR RELEASE

Date of Incident: <u>Historical</u> Facility Name & No: <u>Johnson #3</u>	County: <u>Weld</u>
Type of Facility (well, tank battery, flow line, pit): <u>Tank Battery</u>	QtrQtr: <u>NENW</u> Section: <u>19</u>
Well Name and Number: <u>Johnson #3</u>	Township: <u>5N</u> Range: <u>63W</u>
API Number: <u>05-123-14433</u>	Meridian: <u>6th</u>
Specify volume spilled and recovered (in bbls) for the following materials: Volume is Unknown	
Oil spilled: <u>Unk</u> Oil recov'd: <u>      </u> Water spilled: <u>Unk</u> Water recov'd: <u>      </u> Other spilled: <u>      </u> Other recov'd: <u>      </u>	
Ground Water impacted? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Surface Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Contained within berm? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Area and vertical extent of spill: <u>      </u> Water Vault Area 15' x 15'
Current land use: <u>Tank battery area / Irrigated ground bordering</u> Weather conditions: <u>wet 50's</u>	
Soil/geology description: <u>Bankard Sandy Loam</u>	
IF LESS THAN A MILE, report distance IN FEET to nearest ... Surface water: <u>2325' S Platte</u> wetlands: <u>NA</u> buildings: <u>2000' S</u>	
Livestock: <u>NA</u> Water wells: <u>1195' NE</u> Depth to shallowest ground water: <u>5'</u>	
Cause of spill (e.g. equipment failure, human error, etc.): <u>Equipment Failure</u> Detailed description of the spill/release incident:	
Historical contamination encountered during pit closure procedure. Soil sample tested ND but water sample tested 22 ug for Benzene. LTE will be retained to evaluated site for monitoring wells.	

### CORRECTIVE ACTION

<b>Describe immediate response (how stopped, contained and recovered):</b> All production equipment has been removed from the site. Well has been P&A'd.
<b>Describe any emergency pits constructed:</b> NA
<b>How was the extent of contamination determined?</b> Water vault was removed and 1 soil sample and 1 water sample was taken @ 4'. Confirmation samples showed ND on the soil sample but 22 ug Benzene on the water sample.
<b>Further remediation activities proposed (attach separate sheet if needed):</b> Work wit LTE to determine extent and source of the water contamination.
<b>Describe measures taken to prevent problem from reoccurring:</b>

### OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).

Date	Agency	Contact	Phone	Response
11/2/2009	COGCC	John Axelson		E-mail
11/3/2009	Landowner	Kevin Oschner	x	

Spill/Release Tracking No: \_\_\_\_\_