



Location *Gremlin 23-35*



SURFACE USE: *TIMBER*

NOTE:
FOOTAGES GIVEN ARE ONLY ESTIMATES BASED ON SUBDIVISION PLATS AND TIED TO EXISTING CONTROL. A FULL BOUNDARY SURVEY IS REQUIRED TO DETERMINE TRUE SUBDIVISION LOT AND ROAD LOCATIONS, DISTANCES AND AREA OR FOOTAGE CALCULATIONS.

DATE: December 16, 2009



SHIELDS SURVEY L^{td.} C^{o.}
Raton, New Mexico 87740
(575)445-1232