

**OXY USA WTP LP –  
OPERATOR NO. 66571**

**HYDROTEST NOTIFICATION FORM**

**Type of Pit:**

Flare Pit	<input type="checkbox"/>	Surface interval/well control	<input type="checkbox"/>
Blooney Pit	<input type="checkbox"/>	Reserve Pit	<input checked="" type="checkbox"/>
Flowback Pit	<input type="checkbox"/>	Cement returns Pit	<input type="checkbox"/>
Water Storage Pond	<input type="checkbox"/>	Other (Specify)	<input type="checkbox"/>

**Pit Information**

Pit Name: <b>16A-II Reserve Pit</b>	Pit Location (Common Name): <b>697-16A-2 Pad</b>
API Number (of Associated Well): <b>05-045-17051-00</b>	
Location (Qtr. Qtr, Section, Township, Range, Meridian): <b>NWSW, S16, T6S, R97W, 6th</b>	
Latitude: <b>39.521756</b>	Longitude: <b>-108.231503</b>
Is pit located within ¼ mile of Rim of the Roan Plateau: <b>YES</b>	

**Hydrotest Parameters**

Inspector Name (Print):	Signature:		
Beginning hydrotest time/date: <b>07 Jan 2010 0330 hrs.</b>			
Beginning hydrotest fluid level (feet): <b>8'</b>			
Completed hydrotest time/date: <b>10 Jan 2010 0330 hrs.</b>			
Completed hydrotest fluid level (feet): <b>8'</b>			
<b>Weather Conditions:</b>	<b>Day 1</b>	<b>Day 2</b>	<b>Day 3</b>
Ave. Temperature:	14° AM 26° PM	10° AM 15° PM	25° AM 32° PM
Cloudiness/Wind:	Ptly cloudy / Lt. breeze	Cloudy / Windy	Sunny / Calm
Precipitation:	None	None	None
Humidity:	Low	Low	Low
Did fluid level change after 72-hour hydrotest?	<b>NO</b>		
<b>If yes: RECONSTRUCT PIT AND RECOMPLETE HYDROTEST</b>			
If no: Date of pit operation: <b>10 Jan 2010 0400 hrs.</b>			

Were pictures taken during hydrotest? YES

Additional notes of hydrotest:
