



DEPARTMENT OF NATURAL RESOURCES

Bill Ritter, Jr., Governor
1120 Lincoln St. Suite 801
Denver, CO 80203
Phone: (303) 894-2100
FAX: (303) 894-2109
www.colorado.gov/cogcc

February 19, 2010

Mr. Melvin Dinner
Attorney at Law
822 7th Street, Suite 540
Greeley, Colorado 80631

RE: Segal Tank Battery – Machii-Ross
Section 24, T4N, R66W
Weld County, Colorado
COGCC Remediation No. 3863

Dear Mr. Dinner:

Pursuant to your February 17, 2010 letter, the Colorado Oil and Gas Conservation Commission (COGCC) is overseeing the clean-up (remediation) of soils and shallow ground water at the location identified above. This work is under COGCC remediation number 3863. According to the cover letter submitted with each monitoring report for this work, you are identified as receiving a copy via Howard Boigon. I have attached a copy of the cover letter for the most recent status report (November 24, 2009) with you identified as a copy recipient. If you are not receiving these status reports, please contact Machii-Ross to rectify the situation. Additionally, all document and information pertaining to remediation is available as scanned images through the COGCC web page under COGCC remediation Number 3863, and I refer you to these scanned documents for the work conducted to date.

Respectfully,

Robert H. Chesson, C.P.G., P.G.
Environmental Protection Specialist

SENT VIA EMAIL (robert.chesson@state.co.us)

1103 Oak Park Drive, Suite 110
Fort Collins, CO 80525
Phone (970) 377-1600
Fax (970) 377-1880
www.paragoncg.com

November 24, 2009

Mr. Robert Chesson

Colorado Oil & Gas Conservation Commission, Department of Natural Resources

1120 Lincoln Street, Suite 801

Denver, Colorado 80203

DAVID M. RAU, P.E., BCEE
SCOTT A. RUTHERFORD, P.E.
BRICK SMITH, P.E.
BRAD C. WOHLER
AMY D. WEBER, P.E.
HEATHER S. ALDERMAN
DAVID L. WALKER

RE: August 2009 Quarterly Monitoring Report

Segal Tank Battery (API Number 05-123-09053)

NW ¼ of Section 24, Township 4 North, Range 66 West

County Road 44 and County Road 35

Weld County, Colorado

Project Number 1006006

Dear Mr. Chesson:

Enclosed is the August 2009 Quarterly Monitoring Report for the above-referenced site. Please read the attached report for a summary of the groundwater-sampling activities performed at the site in August 2009. If you have any questions or require additional information, please contact us.

Sincerely,

PARAGON CONSULTING GROUP, INC.



Amy Weber, P.E.

Project Engineer



David M. Rau, P.E., BCEE

Principal Engineer

ADW/DMR:adw1

enc: August 2009 Quarterly Monitoring Report

cc: Machii-Ross Petroleum Company

Mr. Andy Peterson/Peterson Energy Management (via email)

Melvin Dinner, Esq./Melvin Dinner, P.C. via Howard Boigon, Esq./Hogan & Hartson, LLP (via email)

Ms. Katy Evans via Andy Peterson/Peterson Energy Management