

# Location for Sabo 21-22


THERE ARE NO VISIBLE IMPROVEMENTS LOCATED WITHIN 400' OF PROPOSED WELL SITE



**NOTE:**

FOOTAGES GIVEN ARE ONLY ESTIMATES BASED ON SUBDIVISION PLATS AND TIED TO EXISTING CONTROL. A FULL BOUNDARY SURVEY IS REQUIRED TO DETERMINE TRUE SUBDIVISION LOT AND ROAD LOCATIONS, DISTANCES AND AREA OR FOOTAGE CALCULATIONS.

Date: October 14, 2010



**SHIELDS SURVEY Ltd. Co.**  
619 South 2nd Street  
P.O. Box 639  
Raton, New Mexico 87740  
Phone: 445-1232 Fax: 445-3648