

<<< Fold Here >>>

All interpretations are opinions based on inferences from electrical or other measurements and we cannot and do not guarantee the accuracy or correctness of any interpretation, and we shall not, except in the case of gross or willful negligence on our part, be liable or responsible for any loss, costs, damages, or expenses incurred or sustained by anyone resulting from any interpretation made by any of our officers, agents or employees. These interpretations are also subject to our general terms and conditions set out in our current Price Schedule.

Comments

Database File: mcgahey state # 1.db
Dataset Pathname: pass2
Presentation Format: scbl_dlt
Dataset Creation: Wed Nov 18 08:27:51 2009 by Log Std Casedhole 07122
Charted by: Depth in Feet scaled 1:240

0	Collar Locator	-1	0	Amplitude (mV)	100	200	VDL	1200
0	Gamma Ray (GAPI)	180						



0	Collar Locator	-1	0	Amplitude (mV)	100	200	VDL	1200
0	Gamma Ray (GAPI)	180						