



NOTICE: According to Colorado Law, you must commence any legal action based on any defect in this survey within three years after you first discover such defect, in no event may any action be commenced more than ten years from the date of certification shown hereon.

+/- 2.54 ACRE PAD SITE  
 +/-3.40 ACRE DISTURBANCE AREA

SunTerra Oil-Gas LP					TYPICAL RIG LAYOUT ROBERT WALTRIP 1H-3		DOWLING LAND SURVEYORS, LLC P.O. BOX 954 HAYDEN, COLORADO 81639 (970) 276-3613 dowling@plotz.biz		
					SECTION 3, T6N R87W, 6th P.M. ROUTT COUNTY, COLORADO				
SCALE	DRG	DATE	FILE		600' FSL	600' FWL			
1" = 60' GRD		11/26/10	XNPSITE2						